

ONYX[™] Series General Purpose Bench Scale

Model: 6000



© 2000 by Fairbanks Scales Inc. All rights reserved

Amendment Record

ONYX[™] Series

Models: 18899,19810,18900,18901,18902,19816 Manual # 50562

> Manufactured by Fairbanks Scales Inc. 821 Locust Kansas City, Missouri 64106

Created 3/00

Issue #1 3/00

Table of Contents

Section 1: Introduction	5
Section 2: Description A. Certification B. Specifications C. Peripherals	5 5 7
Section 3: Installation A. The Onyx [™] with Short or Tall Pillar B. Detached Wall-mount, or Desk-mount, Display with separate platform	8
Section 4: Programming	10
A. Info Menu B. I / O Menu C. Setup Menu	12 13 15
Section 5: Operation A. Key Functions B. Weighing Operation 1. Gross Weighing 2. Net Weighing 3. Gross/Tare/Net Weighing 4. Piece Counting 5. Checkweighing	16 19 19 19 19 21
Section 6: Troubleshooting A. Error Codes	23
Appendix I: Data Output Specifications, Computer Appendix II: Cable Connection Chart for ONYX™ Scales Appendix III: Printer Setups Appendix IV: Flow Chart	24 27 28 . 33

Disclaimer

Every effort has been made to provide complete and accurate information in this manual. However, although this manual may include a specifically identified warranty notice for the product, Fairbanks Scales makes no representations or warranties with respect to the contents of this manual, and reserves the right to make changes to this manual without notice when and as improvements are made.

Models and Accessories:

<u>Model</u>	<u>Size</u>	Capacity	Description
18899	12" x 12"	6 lb	Platform only
19810	12" x 12"	12 lb	Platform only
18900	12" x 12"	25 lb	Platform only
18901	14" x 14"	60 lb	Platform only
18902	14" x 14"	100 lb	Platform only
19816	14" x 14"	150 lb	Platform only
<u>Accessory</u>	<u>Size</u>	<u>Capacity</u>	Description
20377	12" x 12"	All	Stainless Steel Platform Cover
20378	14" x 14"	All	Stainless Steel Platform Cover
20381	14" x 14"	100,150 lb	Roll Top Conveyor
20890	All	All	Extension Cable, 10', Platform to Display Indicator
20314	All	All	Indicator Keypad Spill Covers (1)
20384	All	All	Indicator Keypad Spill Covers (pkg 10)
21133	All	All	Cable for "On-Line Pro"
_	•	•	
<u>Accessory</u>	<u>Size</u>	<u>Capacity</u>	Indicator w/ Pillar Kit
19807	All	All	Indicator, Short pillar kit
19672	All	All	Indicator ONLY for Wall or Desk mount

Section 1: Introduction

The Onyx[™] bench scale is constructed of a thermoplastic polyester resin composite material and has capacities from 6 lbs to 150 lbs. The intended usage is as a general purpose scale in non-washdown applications.

WARNING: State Weights and Measures agencies will NOT accept ANY scale as a commercial weighing device until it has been "placed in service" by a licensed scale technician / agency. For commercial applications, please call our National Dispatch @ 1-800-332-1123

Section 2: Description

The Onyx[™] bench scale is available in 12" x 12" or 14" x 14". The base has unique "handholds" for picking up and moving the base assembly easily. The display can be ordered with wall-mount, desk-mount or pillar. The pillar height is adjustable for easy viewing. The user can choose the method of powering the scale with AC power, or battery-power by using 6 "D" cells (pillar mount only) housed in the column. The system consists of four (4) wing beam load cells per platform combined with four A-D circuits, offering superior accuracy. The A-D electronics are encased in a 'Pod' within the platform structure for protection and ease of maintenance. All units have built-in counting scale and over/under features. An RS-232 output for a wide range of Fairbanks printers and computers is factory installed.

A. Certification: NTEP CoC 99-197 (12/99) CWM PENDING

B. Specifications:

1. Minimum division sizes for commercial applications:

<u>Model</u>	<u>Size</u>	Capacity	<u>lb</u>	<u>oz</u>	kg	g
18899	12" x 12"	6 lb	6 x .002	96 x .05	2.72 x .001	2720 x 1
19810	12" x 12"	12 lb	12 x .005	192 x .1	5.44 x .002	5440 x 2
18900	12" x 12"	25 lb	25 x .01	400 x .2	10.88 x .005	11300 x 5
18901	14" x 14"	60 lb	60 x .02	960 x .5	27.12 x .01	27150 x 10
18902	14" x 14"	100 lb	100 x .05	1600 x .5	45.40 x .02	45400 x 20
19816	14" x 14"	150 lb	150 x .05	2400 x 1	68 x .02	68000 x 20

2. Construction: Thermoplastic Polyester Resin, modular

3. Overload protection: 300% of scale capacity

4. Environmental: Humidity, 0-90%

Temperature, -10°C to +40°C

5. Power:

- AC: There must not be more than 0.2 vac between AC neutral and ground. For proper performance, the ground should have no more than 3.0 ohms resistance to true earth ground. 117 or 220 VAC, 50-60 Hz +/- 2Hz
- NOTE: For 220VAC operation, see 220V Option*, this page DC: 6 user replaceable "D" cell batteries
- 6. Battery Life: 50+ hours average using "off the shelf" Alkaline batteries
- 7. **Power failure protection:** Calibration and program data is protected during power loss
- 8. Display: Backlit 0.45", 6 digit LCD with indicators
- 9. Center-of-Zero: Active when scale is stable within ¼ division of zero
- 10. Zero: Programmable 2% or 100%
- 11. Units: Front panel selectable lbs., kgs., oz., g, lbs-oz
- 12. Rounding: Nearest division (per Handbook 44).
- 13. Counting: Counting program included, can be programmed ON or OFF
- 14. **Check Weighing:** Graphic display for Over/Under program included, can be programmed ON or OFF
- * 220V Option: Units are shipped with jumpers in place for 117VAC operation unless 220V option is requested at order entry. To change from 117V to 220V:
 - Ensure unit is NOT powered.
 - Remove all indicator screws, cover, and and cable connectors.
 - Locate JP1 (see drawing), REMOVE JP1 jumpers at positions "A" & "C"
 - Place 1 of the jumpers on JP1 position "B", marked "B 220V"
 - Plug all connectors into the PCB, screw case together using these torques (4+2/-0 inch lbs.)
 - Replace AC plug, change serial label to reflect 220V operation.



Important: Save all shipping cartons for future use. In the unlikely event this unit needs factory service, a correctly packed, and labeled scale in the original carton will assure a prompt repair and return.

C. Peripherals:

The Onyx[™] is designed to operate Fairbanks' equipment and interface to computers through a single, programmable RS232 port.

RS-232 features:

- Adjustable Baud Rate
- Adjustable Parity
- Adjustable Stop Bits
- Adjustable Data Bits
- Continuous / Demand / Polled
- Compatible with UPS "Online Pro" software

Tape Printer:

3550 Series Tape Printer (20481)

Label Printer:

PTR-2642 Label / Barcode Printer (19869)

Ticket Printer(s):

PTR-3950	(15733)
PTR-3960	(15737)
610	(19455)

Form Printer:

50-3921 (14322)

Generic:

Computer Printers

Section 3 : Installation

A. The Onyx[™] with short or tall pillar:

1. Place the base assembly UPSIDE down (feet UP) on a solid workplace with the pillar mounting tab over the edge.



- 2. With the scale display facing the platform, hold the pillar under the pillar mounting tab of the base, and feed the plugs and cables from the display up through the hole in the pillar tab of the base.
- 3. With the scale display facing the platform, use the two (2) included screws to fasten the pillar to the base. Ensure that the cables are not 'pinched' but do NOT tighten the screws.
- 4. Locate the small metal bracket, (enclosed in a manila envelope), remove the left pillar mounting screw (scale upside down, pillar facing you).
- 5. Place the bracket so the strain relief on the AC power cord "snaps" into it. The pillar screw will go through the small hole and fasten it and the pillar. Tighten both pillar mounting screws to 20, ±2 inch pounds. Mate the 9 pin connector from the display pillar with the 9 pin connector in the base, (see drawing on page 10). Tighten the small screws to secure the connection.

- Place the assembly upright. Adjust the pillar to a convenient height by
 pressing the release on the back, sliding the pillar up, or down.
 Loosen the rounded knobs on either side of the instrument to tilt the display for
 optimal viewing, then snug, (hand-tighten only). Level the base using the adjustable
 feet and bubble level.
- 7. To use DC power (batteries), install as follows, using the diagram below:
 - Pressing the release and fully extending pillar to top-most position
 - Remove the middle cover that is now visible from the pillar, by loosening the screws (battery cover has 2 slot head screws).
 - Insert 3 "D" batteries on the left side (facing the back) with the (-) ends DOWN, and 3 "D" batteries on the right side (facing the back) with the (+) ends DOWN. Note: Insert the bottom battery, then the top , hold it, then the center battery.
 - Replace the battery cover and snug the screws.
 - The AC power cord may be coiled and tied for future use, or, cut away completely if you will use only battery power in the future.



Note: If the cord is cut away, this is NOT a warranty issue for future AC usage.

- 8. With scale base level, pillar cover in place, batteries inserted -or- AC power cord plugged into an outlet, and platform empty, press the ON/OFF key.
- 9. Display will cycle through an alpha-numeric display test then show 0.00 * (zero).
 - * Scale display will show the weight on the platform (and may show a weight other than 0.00). Remove all weight from the platform and press ZERO to set scale to 0.00

B. Detached wall-mount, or desk-mount: display with separate platform

1. Use cable accessory 20890 to make the platform to display connection. Turn the platform up-side-down, then mate the 9 pin connector from the display pillar with the 9 pin connector in the base. Tighten the small screws on the connector to secure the connection. See the following Diagram # 50561-3e.



- 2. Place the platform on a solid, level work place where it will be used.
- 3. Mount the display mounting bracket (18207) to the wall, using the screws (be sure the bracket is level for best viewing). For desk-mount the bracket is screwed to a counter top, or left loose and set onto a surface.
- 4. Route cable 20890 from the display to the base so it is protected.
- 5. Loosen the knobs on either side of the instrument to tilt the display for optimal viewing, hand-tighten ONLY.
- 6. With scale base level, AC power cord plugged into an outlet, and platform empty, press the ON/OFF key.
- 7. Display will cycle through an alpha-numeric test display, then should show 0.00 * (zero).
 - * If a display other than 0.00. Remove all weight from the platform and press ZERO to set scale to 0.00
- *Important:* Save all shipping cartons for future use. In the unlikely event this unit needs factory service, a correctly packed, and labeled scale in the original carton will assure a prompt repair and return.

Section 4: Programming

Onyx[™] programming is divided into menus. Each menu has entries that may be viewed, changed, and saved.

INFO:

set: display contrast sleep time show: audit counts cell counts print report

IO:

set: time date device RS232 settings items to be printed autoprint

SETUP:

set: counting (pcwt) checkweighing (o/u) units tares filter display rate

Special Key Functions: (Key definitions are explained in Section 5, Operation, page 16)

- In the program mode, the GR/NT key aborts to the gross weigh mode
- In the program mode, pressing the Pgr key will return to the top of the present menu
- When entering data, any mode, pressing the decimal point (.) twice will clear the entry

Passwords:

Passwords may be set for the protected menus:

CANNED IO SETUP CAL

There may be 4 different numeric codes for different levels of access. Menu access will require the proper code to be entered to continue.

A. INFO menu:

- Press the Pgr key, the display will show "INFO MENU"
- Press ENTER, the display will show "DISPLAY CONTRAST"
- To darken the display:
 press the **APPLICATION** key until it is the desired contrast
- To lighten the display: press the **PRINT** key until it is the desired contrast
- Press ENTER, the display will show "SLEEP TIME" This is used for battery operation, the time represents the elapsed time of 'no weighing activity' before 'sleep' starts
- Enter the **time, in minutes,** (decimals for seconds), using the numeric keypad, press **ENTER**, 0 = Disabled, any other value enables 'sleep'.
- The display will show "CONFIG AUDIT XX", count of configurations performed, press ENTER (used by most regulatory agencies)
- The display will show "CAL AUDIT XX", count of the calibrations performed, press ENTER (used by most regulatory agencies)
- The display will show "XXXX COUNTS CELL 1", press SCROLL to view other cells' counts
- Press ENTER, the display will show "REPORT hit PRINT". Press PRINT to send the data to an installed device.
- Press ENTER to exit to the weigh mode.

- Press the **Pgr** key, the display will show "**INFO MENU**" press **SCROLL** twice
- The display will show "IO PASSWORD" Enter the password (up to 6 digits), press ENTER
- The display will show "TIME X:XX:XXAM" To enter a new time: key in the hour, press the decimal (.) for the colon, key in the minutes and press ENTER. The display will show the entered time. Use SCROLL to set the AM / PM or, no legend for military time, press ENTER
- The display will show "DATE XX-XX-XXXX" To set the date, key in the month, press the decimal (.), key in the day, press the decimal (.), then key in the 4 digit year, press ENTER
- The display will show "DEVICE: 3550" Use SCROLL to view the list of devices: 3550, 3950, 3960, 610, 3921, 2642, 2642BARCD, GENERIC, CONTINUOUS, POLLED, ONLINEPRO
- Press ENTER to accept selection of DEVICE
- The display will show "STD SETTINGS:YES", use SCROLL to change, press ENTER
- The display will show "BAUDRATE: 9600", use SCROLL to change, press ENTER
- The display will show "DATA BITS: 8", use SCROLL to change, press ENTER
- The display will show "STOP BITS: 1", use SCROLL to change, press ENTER
- The display will show "PARITY: NONE", use SCROLL to change, press ENTER
- The display will show "**PRINT TIME: YES**", use **SCROLL** to change, press **ENTER**
- The display will show "**PRINT DATE: YES**", use **SCROLL** to change, press **ENTER**

- The display will show "**PRINT GR TA NET**", use **SCROLL** to change, press **ENTER**
- The display will show "**PRINT ID: YES**", use **SCROLL** to change, press **ENTER**
- The display will show "PRINT PIECES: YES", use SCROLL to change, press ENTER
- The display will show "**PRINT PC WT: YES**", use **SCROLL** to change, press **ENTER**
- The display will show "AUTO PRINT: NO", use SCROLL to change, press ENTER
- The display will show "**PRINT SWT: YES**", use **SCROLL** to change, press **ENTER**
- The display will show "SETUP PASSWORD", press ENTER to continue to SETUP
- To exit programming press B/G/NET
- **Note 1:** When the "**DEVICE**" is selected, the "**STD SETTING**" will revert to the default serial setup for that device type. In the same menu, "**PRINT XXXX: YES**" will print the item while a "**NO**" will omit the item from the transmission to a printer or computer.
- **Note 2:** "**AUTOPRINT**" has a threshold of 10 divisions. That is, if the weight is at least 10 divisions, and stable, a print will occur. Before "**AUTOPRINT**" will print again, the weight must fall to less than half the weight display. Check the particular operation at the customer site for Autoprint usage.
- **Note 3:** If "**AUTOPRINT**" is set to "**YES**", the next legend will be "**PRINT SWT: YES**". This means the print switch on the keypad is enabled. If set to "**NO**", the print switch is disabled.

C. SETUP menu:

- Press the Pgr key, the display will show "INFO MENU", press SCROLL three times.
- The display will show "SETUP PASSWORD", Enter the password (up to 6 digits), press ENTER
- The display will show "PIECE COUNT: YES", use SCROLL to change, press ENTER
- The display will show "OVER/UNDER: YES", use SCROLL to change press ENTER
- The display will show "ENABLE Ib: YES", use SCROLL to change press ENTER
- The display will show "ENABLE kg: YES", use SCROLL to change press ENTER
- The display will show "ENABLE oz: NO", use SCROLL to change press ENTER
- The display will show "ENABLE g: NO", use SCROLL to change press ENTER
- The display will show "ENABLE Ib-oz: NO", use SCROLL to change press ENTER
- The display will show "AUTOTARE: YES", use SCROLL to change press ENTER
- The display will show "KEYBD TARE: YES", use SCROLL to change press ENTER
- The display will show "FILTER: LIGHT", use SCROLL to change press ENTER
- The display will show "DISPLAY RATE: 0.3" (minimum), use NUMERIC keys to change rate, press ENTER to continue into CALIBRATION
- To exit programming press **B/G/NET** key.

Section 5: Operation



A. Key Functions:

ON/OFF - Pressing this key will toggle the scale ON / OFF



APPLICATION KEY - Pressing this key toggles the scale operation mode from WEIGH -to- COUNTING -to- OVER/UNDER

Using the Application Key

In the INFO menu, with "DISPLAY INTENSITY" showing, pressing the Application key repeatedly will darken the display contrast.



PROGRAM - Pgr - In the WEIGH mode: Press Pgr to enter PROGRAMMING In the PROGRAM mode: Press Pgr to return to the first menu item In the PCWT mode: Press Pgr to toggle SPL SIZE -to- PCWT In the OVER/UNDER mode: Press Pgr to enter Target weights



SCROLL - In the WEIGH mode: Press scroll to prompt for ID In the PROGRAM mode: Press scroll to view menus In the PROGRAM menus: Press scroll to toggle through parameters In the PCWT mode: Press scroll to toggle PCWT -to- SPL SIZE In the OVER/UNDER mode: Press scroll to toggle contrast of the bar graph In TARGET WEIGHT: Press scroll to toggle SAMPLE TARGET WT

Using SCROLL for ID:

From the weighing mode, pressing SCROLL will toggle the ID legend ON / OFF. Pressing numeric keys 0-9 (up to six (6) digits) with the ID legend displayed, will enter an ID for a unique customer or container number.

Example: Press SCROLL to show ID legend, key in 55147,

then press ENTER; 55147 is temporarily stored as an ID.

ID can then be printed to identify a weighment.

From the counting mode, press SCROLL to toggle between piece weight and the weight on the scale GR (gross or NET weight if a Tare is entered).



PRINT - Press print to send data to an installed printer

Using PRINT:

Pressing the PRINT key will cause weight data to be sent to an attached receiving device (set up in programming). In the INFO menu, with "DISPLAY INTENSITY" showing, pressing PRINT several times will lighten the display



GROSS/NET - In the WEIGH mode: Press to toggle GR -to- NET In the PCWT mode: Press to toggle GR -to- NET In the OVER/UNDER mode: Press to toggle GR -to- NET

Using B/G NET

Pressing the B/G NET key will toggle the display from GR (gross) to NET (net) modes of weighing. If a tare is entered, the tare will be active when NET is displayed. The TARE, or ID if selected, will be displayed on the same screen.



UNITS - In the WEIGH mode: Press to toggle through programmed units

Using UNITS

Pressing the UNITS key will toggle through all units choices. When changing units, a different division size, and possibly different decimal places will be shown.



AUTOTARE - In the WEIGH mode: Press to show tare, autotare if enabled In the PCWT mode: Press to autotare if enabled In the OVER/UNDER mode: Press to autotare if enabled

Using AUTOTARE and Tare function

With an empty container or object to be "tared" on the platform, press AUTO TARE, or, enter numeric weight value then press ENTER. The autotare or entered value becomes a stored TARE weight. The tare weight and net weight will be shown whenever the NET mode is entered (pressing B/G NET toggles between GR and NET). Enter "0", then ENTER to set a "0" tare.



ZERO - *In the WEIGH mode:* Press zero to set display to 0.00 while in GR mode *In the PCWT mode:* Press to zero scale while in GR or NET mode *In the OVER/UNDER mode:* Press to zero scale while in GR or NET mode



ENTER - In the WEIGH mode: Press enter to accept manually keyed tare weights In the PROGRAM mode: Press enter to accept the displayed value In the PCWT mode: Press to accept manually entered SPL SIZE In the PCWT mode: Press to accept manually entered piece weight In the OVER/UNDER mode: Press to accept manually entered TARGET, UNDER, and OVER entries



- 0-9 In the WEIGH mode: Use keys to enter tare value (press ENTER to complete) In the WEIGH mode: Press scroll then numeric keys to enter an ID (press ENTER to complete) In the PROGRAM mode: Use to enter PASSWORD, set SLEEP time, (1=yes, 0=no) Enter parameters Enter calibration weight value
- (•) (decimal key) In the WEIGH Mode: Used to enter tare value

In any MODE: Pressing twice will erase keyed entry

B. Weighing Operations:

- 1. Gross Weighing:
 - a. Press B/G NET, if needed, to set display to GR (gross)
 - b. Use ZERO, if needed, to set scale display to 0.0
 - c. Place container/object on scale platform
 - d. If ID is desired, press SCROLL, enter numeric ID, press ENTER
 - e. Record/read GROSS weight
 - f. Press PRINT to send data to an installed printer

2. Net Weighing:

- a. Press B/G NET, if needed, to set display to GR (gross)
- b. Use ZERO, if needed, to set scale display to 0.0
- c. Place container/object on scale (Tare weight)
- d. Press AUTOTARE or enter tare weight via keypad
- e. Place material in container or add objects (net weight)
- f. If ID is desired, press SCROLL, enter numeric ID, press ENTER
- g. Record/read NET weight (tare weight will also be shown on display)
- h. Press PRINT to send data to an installed printer

3. Gross/Tare/Net Weighing:

- a. Press B/G NET, if needed, to set display to GR (gross)
- b. Use ZERO, if needed, to set scale display to 0.0
- c. Place container/object on scale (Tare weight)
- d. Press AUTOTARE or enter tare weight via keypad
- e. Place material in container or add objects (net weight)
- f. If ID is desired, press SCROLL, enter numeric ID, press ENTER
- g. Read NET weight, read TARE weight
- h. Press B/G NET, read GROSS weight
- i. Press PRINT to send data to an installed printer

4. Piece Counting

A piece count is arrived at by dividing the weight, by the piece weight, using a known piece weight reference.

A piece weight is calculated by using a sampling function, or from weighing the piece directly on an appropriate scale. To enter the count mode and verify or set a piece weight:

- From the weigh mode, press the Application key once to enter the counting mode
- The display will show:



- Press SCROLL to display the piece weight
- The display will show:



a. **To use the displayed piece weight,** (saved from a previous setting): Place items on the scale and read PCS (pieces), or, place a container on the scale, press **AUTOTARE**, then put the pieces into the container to count.

• The display will show:



b. To change the piece weight manually:

Press **Pgr**, then **SCROLL**. Enter known piece weight using the numeric keypad, then press **ENTER**.

• The display will show:

>0<		lb
РСѠТ	0.1234567	

Place items on the scale and read PCS (pieces), or, place a container on the scale, press **AUTOTARE**, then put pieces into the container to count.

c. To calculate a new piece weight using a known sample:

- From the weigh mode, press the **Application** key once to enter the counting mode
- The display will show:



- Press Pgr,
- The display will show:



- Count out 25 large items, or aprox. 50 (or more) small items and place them on the scale. (Sample count should always be greater for small items)
- If you use a container, place the empty container on the scale and press **AUTOTARE**
- If current sample size is correct, press **ENTER**, or enter the item count of the sample via the keypad and press **ENTER**
- The display will show:



- Press SCROLL,
- The display will show:



- The new, calculated piece weight will be displayed
- Press **PRINT** to send data to an installed printer
- To exit the counting mode, press the Application key twice

5. Checkweighing:

Checkweighing is used to see 'graphically' if an item placed on the scale falls within an acceptable weight range. The operator merely needs to add product if under, or remove product if over.

a. To set the known target weight ranges for a product:

- From the weigh mode, press the **Application** key twice
- The display will show :

0.00	lb	GR
• ¦ •••••• ! •••••••	••••	
UNDR		

- Press Pgr,
- The display will show:



- Enter the new target weight desired using the numeric keypad,
- The display will show:

-	lb
TARGET	WEIGHT
==>	2.25

- press ENTER
- The display will show:



- Enter the allowable under-weight, press ENTER
- The display will show :



- Enter the allowable over-weight, press ENTER
- The display will show:

2.19 lb G	R
••••••	••••••
ACCEPT	

b. To set an unknown target weight, and ranges for a product:

- While in the Checkweigh mode, press the Pgr key followed by the SCROLL key
- The display will show:



- Place the sample item or product on the platform.
- The display will show:



• Press ENTER,

the weight shown will be accepted as the Target Weight.

• The display will show:



- Enter the allowable under-weight, press ENTER
- The display will show:



- Enter the allowable over-weight, press ENTER
- The display will show:



- An item placed on the scale platform will show "UNDR" until it reaches the TARGET WEIGHT, minus (-) UNDER AMOUNT, then show "ACCEPT".
- The display will show "OVER" when it reaches the TARGET WEIGHT plus (+) OVER WEIGHT.
- The display will show "ACCEPT" when the weight value is between the two entered parameters

Section 6: Troubleshooting

A. Error Codes:

<u>Display</u>	Meaning	Remedy
"automatic reset"	momentary	Resetting upon powerup, no remedy needed.
"automatic reset"	Continuous	Display to Pod connection problem, check 9 pin plug(s), cable, then recycle power.
	QTY is Negative	With platform and/or container empty, press ZERO (gross mode) or AUTOTARE (net mode), resume count operation.
	Value is > 6 digits	Display is exceeding its 6 digit capability. Division size may be set to an improper value, reset division size.
"over capacity"	Over capacity	Remove load, load value exceeds physical or programmed capacity of the platform.
"over ld corner x"	Corner overloaded	Place weight in the center of the weigh platform.
"qty is excessive"	> than 6 digits	The display can show 6 digits of weight or count (999,999), this count has been exceeded.
"Error, PCWT=0"	No PCWT	There is no value for piece weight entered. Enter piece weight manually or by placing a sample on the scale. (See Section 5/b/4/c, pg 19).
"replace batteries"	Low battery power	Replace batteries per instructions in Section 3. Scale will NOT operate, due to low power.
"BAT"	Low battery power	Replace batteries per instructions in Section 3.

Appendix I: Data Output Specifications, Computer

(Generic, Continuous, Polled, On-Line Pro)

A. Introduction: The single RS232-C output port is designed for interface with Fairbanks equipment as well as customer's data processing equipment.

B. Specifications:

RS232-C Compatible Data Signal Data Bits: 7 / 8 Parity: Odd / Even / None Baud Rate: 9600, 4800, 2400, 1200, 600 Stop Bits: One / Two US-ASCII Character Set Mark = -3 to -15V Space = + 3 to +15V Maximum distance of 50 cable-feet

C. Character Frame: Characters are transmitted in an ASCII format at selectable baud (+0.1%). The receiver must be capable of a tolerance of 9600 (± 2.5%) Baud to allow for line losses and frequency skew. Character frame consists of one start bit, 7/8 bit character length, selectable parity bit and one / two stop bits.

3 to 15 VDC ON State (Spacing)	S T R T B I T	D 0 L S B	D 1	D 2	D 3	D 4	D 5	D 6	P A I T Y B I T	S T O P B I T	S T P B I T	
Logic State -3 to -15 VDC OFF State (Marking)	0 ON									0 OFF	0 OFF	1937c

NOTES:

Least Significant Bit (LSB), D0 transmitted first. Space Character + HEX 20. Voltage levels above +15 VDC are invalid. Voltage levels below - 15 VDC are invalid. Voltage levels between -2 and +2 are invalid.

D. Data Transmission:

On-Line-Pro: Data is transmitted on DEMAND to the host device. Data available for transmission consists of the GROSS weight. Transmission to the host will occur when the host transmits a Carriage Return (HEX 0D) to the scale.

Character Number	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
String 1																		
Gross Weight	х	Х	Х	х		х	Х	SP	l/k	b/g	SP	G/g	R/r	SP	SP	CR	LF	EOT

NOTES:

- 1. Characters denoted by "X" are characters 0-9. Leading zeroes are replaced with spaces (SP). Character 5 is a decimal point (HEX 2E).
- 2. Lower case "I" and "b" for Avoirdupois Units or "k" and "g" for Metrics Units.
- 3. The first weight character will be a minus (-), HEX 2D, If weight is negative.
- 4. Characters separated with a "/" denotes **ONLY** one of the characters will be transmitted.
- 5. Lower case gr in characters 12 &13 indicates scale motion. Upper case indicates stable weight.
- 6. EOT, HEX 04 is transmitted in "HiCAP" condition.
- 7. Transmission will occur when a CR (Hex 0D) carriage return is received.

Data as 'seen' by the receiving device:

-0.50	LB	GR
0.5050	LB	GR
0.50	LB	GR
1.50	LB	GR
11.50	LB	GR
10	LB	GR

E. Data Transmission, Polled, Continuous, or Generic:

Polled: Data is transmitted when a CR is received by the Onyx **Continuous:** Data is transmitted without initiation by the operator or receiving device **Generic:** Data is transmitted by pressing the PRINT key

Data String consists of the following: (this is one continuous string of alpha characters)

cr Time: tt: tt AM cr lf Date: dd- dd- dddd cr lf ld: iiiiii cr lf lf www.ww lb GR cr lf www.ww lb TA *cr lf www.ww lb NT cr lf lf cr lf cr lf

- t time character = d date character = i id character = weight character w = cr carriage return = lf line feed =
- Note: The data string is the same in all of these modes. Items may be omitted from print or send by selecting ""NO" in the I/O menu. When prompted for "PRINT XXXX: YES, change to "NO" using the SCROLL KEY, then press ENTER.

Data as "seen" by the receiving device:

Time	: 11:18:4	3AM
Date:	02-24-2	000
id:	568922	
	2.16 lb	GR

1.00 lb TA 1.16 lb NT

Appendix II: Cable connection chart for Onyx[™] Scales:

A. Cable Pin-Outs

Onyx™	3550	3950	3960	610	3921	2642	Cputr	Cputr
TB2	DB25	DB25	DB25	DB25	DB25	DB9	DB25	ĎB9
Internal	Male	Female						
RX1			2				2	3
TX 2	3	3	3	3	3	3	3	2
CTS 3	20				20			
GND 4	7	7	7	7	7	5	7	5
RTS 5								
Cable#	15597	15598	15599	15598	15599	21052	15599	21133

Appendix III: Printer Setups

A. 3550 Series Tape Printer Settings:

SW1 = 0111010100 **SW2** = 11111100

9600, No parity, 8 Bits, 1 Stop Use Cable # 15597 (Acc 1295)

Print Examples

Pc Weight w/GTN & ID		<u>GTN</u>	<u>w/ID</u>	<u>Net/GR Only w/ID</u>		
Time:	10:57:11AM	Time:	10:57:11AM	Time:	10:57:11AM	
Id:	11	Id:	11	Id:	11	
11.70	lb GR	11.70	lb GR			
6.70	lb TA *	6.70	lb TA *			
5.00	lb NT	5.00	lb NT	5.00	lb NT	
Qty:	500					

Pc. Wgt. 0.0100

B. PTR-3950 Ticket Printer Settings:

SW1	12345678	SW2	12345678
	01100011		10011010

2400, No Parity, 8 Bits, 1 Stop Use Cable 15598 (Acc 1296)

Print Examples:

Pc Wei	<u>ght w/GTN & ID</u>	<u>GTN</u> v	<u>v/ID</u>	Net/GR	Only w/ID
Time:	12:10:01PM	Time:	12:10:01PM	Time:	12:10:01PM
Date:	01-31-2000	Date:	01-31-2000	Date:	01-31-2000
Id:	1	Id:	2	Id:	3
11.00	lb GR	11.00	lb GR	5.00	lb GR
6.00	lb TA *	6.00	lb TA *		
5.00	lb NT	5.00	lb NT		

Qty: 500 Pc. Wgt. 0.0100

C. PTR-3960 Ticket Printer Settings:

SW1 12345678910 1110000000

9600, No Parity, 8 Bits, 1 Stop Use Cable 15599 (Acc 1297)

Print Examples:

Pc Wei	ight w/GTN & ID	GTN v	w/ID	Net/GF	R Only w/ID
Time:	12:10:01PM	Time:	12:10:01PM	Time:	12:10:01PM
Date:	01-31-2000	Date:	01-31-2000	Date:	01-31-2000
Id:	1	Id:	2	Id:	3
11.00	lb GR	11.00	lb GR	5.00	lb GR
6.00	lb TA *	6.00	lb TA *		
5.00	lb NT	5.00	lb NT		
Qty:	500				

Pc. Wgt. 0.0100

D. PTR-610 Ticket Printer Settings:

SW1 01010011

1200 Baud, Odd Parity, 7 Bits, 1 Stop Use Cable 15598 (Acc 1296)

<u>Pc Wei</u>	<u>ght w/GTN & ID</u>	<u>GTN</u>	<u>w/ID</u>	<u>Net/GR</u>	Only w/ID
Time: Date: Id:	10:57:11AM 01-31-2000 11	Time: Date: Id:	10:57:11AM 01-31-2000 11	Time: Date: Id:	10:57:11AM 01-31-2000 11
11.70	lb GR	11.70	lb GR		
6.70	lb TA *	6.70	lb TA *		
5.00	lb NT	5.00	lb NT	5.00	lb NT

Qty: 500 Pc. Wgt. 0.0100

E. 50-3921 Form Printer Settings:

SW1(super spd ser bd)	SW2 (super spd ser bd)	DipSW (Main PC)
12345678	12345678	12345678
11111111	01100110	00001010

9600, No Parity, 8 Bits, 1 Stop Use Cable 15599 (Acc 1297)

Print Examples:

Pc Wei	<u>ght w/GTN & ID</u>	<u>GTN</u>	<u>w/ID</u>	<u>Net/GR</u>	Only w/ID
Time:	10:50:01AM	Time:	10:50:01AM	Time:	10:50:01AM
Date:	01-31-2000	Date:	01-31-2000	Date:	01-31-2000
Id:	5	Id:	5	Id:	5
11.70	lb GR	11.70	lb GR		
6.70	lb TA *	6.70	lb TA *		
5.00	lb NT	5.00	lb NT	5.00	lb NT
Qty:	500				

Pc. Wgt. 0.0100

F. PTR-2642 and 2642 Barcode Label Printer Settings:

Note: The 2642 MUST be initialized, as follows:

- 1. Make certain the printer is connected, and is powered before programming the Onyx[™].
- 2. If NOT, connect & power up the 2642, then recycle the Onyx[™] power.

No Switches on PTR-2642 to set! 9600 Baud, No Parity, 8 Bits Use Cable 21052

Print Examples:



CONFIGURATION REPORT (use a form or tape printer) TIME 8:14:40AM DATE 02-08-2000 CONFIG AUDIT: 4 CAL AUDIT: 2 CAPACITY: 150 div SIZE: .05 CAL UNITS: lb TYPE: HANDBOOK44 AZT BAND: 0.5 MOTION BAND: 1.0 PIECE COUNT: YES OVER/UNDER: YES ENABLE lb: YES ENABLE kq: YES ENABLE oz: NO ENABLE g: NO ENABLE lb-oz: NO AUTOTARE: YES KEYBD TARE: YES FILTER: LIGHT DISPLAY RATE:0.3 SLEEP TIME: 0.0 DEVICE: 3550 BAUDRATE: 9600 DATA BITS: 8 STOP BITS: 1 PARITY: NONE PRINT TIME: YES PRINT DATE: YES PRINT GR TA NET PRINT ID: YES PRINT PIECES:YES PRINT PC WT: YES AUTO PRINT: NO PRINT SWT: YES

G. Generic:

Set up the output for any 'other' device in the serial format selected.

H. Continuous:

Set up the output for a continuous output in the serial setup selected.

I. Polled:

A request for data, from a device, is answered by the Onyx[™] in the serial setup selected.

J. OnlinePro:

An output setup that matches the UPS data format, software available at www.UPS.com

9600
7
2
Odd

Use Cable 21133

