# SIF2 SERIES

Intrinsically Safe Digital Weight Indicators

For Chemical, Petroleum, Phamaceutical & other Harsh, Industrial Environments.





Optional Long-life Battery Pack



For More Information on the 3052 and other Fairbanks Intrinsically Safe Products, Visit Fairbanks.com Today!



# **FAIRBANKS**<sup>®</sup>

## **3052 SERIES INTRINSICALLY SAFE DIGITAL WEIGHT INDICATOR**

Fairbanks 3052 Series indicators are intrinsically safe, ultra-low-power instruments. They offer the convenience of a versatile electronic indicator with features required in hazardous areas, eliminating the need for traditional explosion-proof enclosures or purging systems.

### **BATTERY POWER**

Since Fairbanks 3052 Series Digital Weight Indicators are battery powered, they can be used in hazardous areas for up to 50 hours of continuous operation or up to 250 hours if the auto shutoff is activated. When used with the rechargeable battery pack, the 3052 is FM approved for Classes I, II & III, Division 2, Groups A, B, C, D, F & G.

### **DIRECT POWER SUPPLY**

As an alternative power source for certain applications (Groups C, D, E, F and G), you can use Fairbanks' 5816 direct power supply accessory, eliminating the need for a battery.

### **SPECIFICATIONS**

350 ohm cells at 2000 divisions
Pushbutton Zero Range ... 2% or 100% selectable
Data Storage ... 100% retention of calibration
data in non-volatile EEPROM
Humidity ... 0 to 100%; suitable for washdown
Enclosure ... Stainless steel NEMA 4X rated

Humidity ... 0 to 100%; suitable for washdowr
Enclosure ... Stainless steel, NEMA 4X rated
Power Requirements ... 7 volt rechargeable lead-acid
battery pack for 50 hours of

continuous operation


Accessories . . . . . . . . . . Battery pack, direct power

supply, wall/desk mount bracket, rechargers, power supply cables

Approvals . . . . . NTEP CC# 92-050, CSA, MC #AM-4855, FM approved for

Classes I, II & III, Division 2, Groups A, B, C D, F, & G

### **FEATURES**




Rugged NEMA 4X stainless steel enclosure provides protection in harsh washdown environments. Flexible tare capabilities

Auto tare

• Tare entry via keypad

Tare recall

### **DIMENSIONS**



Your Fairbanks Scales Authorized Representative is:

Call toll-free for the representative nearest you:

### (800) 451-4107

Call between 8:00 a.m. – 5:00 p.m. Central Time
Corporate Headquarters: 6800 W. 64th Street, Overland Park, Kansas 66202
(816) 471–0231 Internet Address: http://www.Fairbanks.com

# Service & Installation Manuals:

Fairbanks Scales' intrinsically safe equipment requires special attention to the service and installation manuals. Serious damage could occur if guidelines are not followed.

